

<u>Qty</u>			<u>Item #</u>	<u>PUR Ticket#</u>	<u>Branch</u>	<u>Damage Description</u>	<u>Sell Price</u>	
<u>Fujitsu Mini Split</u>								
1	AOUH36LPAS1		3 Ton Outdoor Unit	119054	DSM	Top/Side dents	\$1,000	S100788065.pdf
1	AOUH36LPAS1		3 Ton Outdoor Unit	119054	DSM	Minor scratches & dents	\$1,000	S100755869.jpg
1	AOU36RLXFZH		3 Ton Outdoor Unit	54322	LEM	No Box	\$850	
<u>Fujitsu Unitary</u>								
1	FO6014RSJNAB		5 Ton 14 Seer Heat Pump	103451	BRN	Dents left side & top	\$2,200	S100795176.pdf
1	FO2414RSJNAA		2 Ton 14 Seer Heat Pump	103446	BRN	No Box	\$1,300	
<u>Ruud HVAC</u>								
1	RH1PZ3017STANNA		2.5 Ton Air Handler	130542	DSM	Partially installed, wrong voltage	\$700	
1	R962V0703A17M4SCAP	96+ 2 Stage 70bktu Multi Pos Furnace		124498	DSM	damage lower left corner	\$1,500	S100763954.jpg
1	R962V0703A17M4SCAP	96+ 2 Stage 70bktu Multi Pos Furnace		124498	DSM	Side damage	\$1,400	S100759372.jpg
<u>Ruud Water Heater</u>								
1	PROG40-38N RU62		40G NG Water Heater	44766	LEM	Dented near bottom	\$350.00	S100759372.jpg
1	GHE80SU130		80G Commercial NG Water Heater	76416	DSM	Dents & Scratches	\$4,700.00	S100728452 Page 1.jpg
1	GHE100SU400A		100G ASME Comm Water Heater	77524	MSC	Side/top damage	\$8,700.00	S100702279.pdf
<u>Schwank</u>								
1	JT-BS18-AN		180K Burner	114395	DSM	Scratches & dents	\$200.00	S100737963.pdf
<u>Weatherking</u>								
1	W962W1005A21M	96% 2 Stage 100KBTU Multi Pos Furnace		128370	SLK	no damage- fired for 2 days, changed to twinned application	\$1,100	
1	W962W1005A21M	96% 2 Stage 100KBTU Multi Pos Furnace		128370	SLK	no damage- fired for 2 days, changed to twinned application	\$1,100	

ALL ITEMS ARE FOR IMMEDIATE SHIPMENT-ALL SALES ARE FINAL