

<u>Qty</u>			<u>Item #</u>	<u>PUR Ticket#</u>	<u>Branch</u>	<u>Damage Description</u>	<u>Sell Price</u>	
	<b><u>Aspen</u></b>							
1	CC60B34-245L	5 Ton Cased Coil	22705	S100857370	DSM	Minor damage	\$200	<a href="#">Image Link</a>
	<b><u>Fujitsu Mini Split</u></b>							
1	AOUH30LPAS1	3 Ton Outdoor Unit	119054	S100788065	DSM	Top/Side dents	\$250	<a href="#">Image Link</a>
	<b><u>Fujitsu Unitary</u></b>							
1	FO6014RSJNAB	5 Ton 14 Seer Heat Pump	103451	S100795176	BRN	Dents left side & top	\$1,000	<a href="#">Image Link</a>
1	FO2414RSJNAA	2 Ton 14 Seer Heat Pump	103446	S100795176	BRN	No Box	\$700	
	<b><u>Lochinvar</u></b>							
1	SIT080	Indirect fired Water Heater	44948	S100823601	DSM	Lost a fight with a forklift	\$900	<a href="#">Image Link</a>
	<b><u>Ruud Water Heater</u></b>							
1	PROE40T2RU95	40G Electric Water Heater	46226	S100866960	DSM	Top damage	\$300.00	<a href="#">Image Link</a>
1	PROE40T2RU95	40G Electric Water Heater	46226	S100866891	DSM	heavy bottom/side damage	\$250.00	<a href="#">Image Link</a>
1	PROE40T2RU95	40G Electric Water Heater	46226	S100867637	DSM	Top/Side dented & scratched	\$350.00	<a href="#">Image Link</a>
1	PROE40T2RU95	40G Electric Water Heater	46226	S100867796	DSM	Top/Side dented	\$350.00	<a href="#">Image Link</a>
1	PROE40M2RU95	40G Electric Water Heater	45804	S100873071	WAU	Top dented	\$250.00	<a href="#">Image Link</a>
1	PROG4040NRU67PV	40G NG Power Vent Water Heater	39281	S100879947	DSM	No box	\$1,200.00	
1	PROE50T2RU95	50G Electric Water Heater	46225	S100883061	OTT	Side damage	\$300.00	<a href="#">Image Link</a>
1	GHE80SU130	80G Commercial NG Water Heater	76416	S100728452	DSM	Dents & Scratches	\$3,100.00	<a href="#">Image Link</a>
1	GHE100SU400A	100G ASME Comm Water Heater	77524	S100702279	MSC	Side/top damage	\$7,200.00	<a href="#">Image Link</a>
	<b><u>AO Smith</u></b>							
1	BTX-100	100G Water Heater	28142	S100821173	COL	dent at bottom	\$1,700.00	<a href="#">Image Link</a>
	<b><u>Weatherking</u></b>							
1	W962W0603A17M4SBAS	96% Two Stage 60KBTU NG Furnace	128366	S100880147	DSM	Side damage minor top damage	\$900.00	<a href="#">Image Link</a>
	<b><u>Weil McClain</u></b>							
1	CGA-5-PIDN	98K NG Boiler	23441	S100881438	SLK	Side/Back damage	\$1,900	<a href="#">Image Link</a>
1	CGA-6-PIDN	127K NG Boiler	12765	See Tim	CDR	Side damage	\$1,700	

**ALL ITEMS ARE FOR IMMEDIATE SHIPMENT-ALL SALES ARE FINAL**