

<u>Qty</u>			<u>Item #</u>	<u>PUR Ticket#</u>	<u>Branch</u>	<u>Damage Description</u>	<u>Sell Price</u>	
	<u>Fujitsu</u>							
1	AOUH36LPAS1	3 Ton Outdoor Unit	119054	S100755869	DSM	Minor scratches & dents	\$1,400	Image Link
1	AOU36RLXFZH	3 Ton Outdoor Unit	54322	S100617192	LEM	No Box	\$1,100	
	<u>Ruud HVAC</u>							
1	R962V0703A17M4SCAP	96+ 2 Stage 70bktu Multi Pos Furnace	124498	S100763954	DSM	damage lower left corner	\$1,900	Image Link
1	R962V0703A17M4SCAP	96+ 2 Stage 70bktu Multi Pos Furnace	124498	S100763835	DSM	Side damage	\$1,800	Image Link
	<u>Ruud Water Heater</u>							
1	PROG40-38N RU62	40G NG Water Heater	44766	S100759372	LEM	Dented near bottom	\$600.00	Image Link
1	GHE80SU130	80G Commercial NG Water Heater	76416	S100728452	DSM	Dents & Scratches	\$5,200.00	Image Link
1	GHE100SU400A	100G ASME Comm Water Heater	77524	S100702279	MSC	Side/top damage	\$9,200.00	Image Link
	<u>Schwank</u>							
1	JT-BS18-AN	180K Burner	114395	S100737963	DSM	Scratches & dents	\$400.00	Image Link
	<u>Weatherking</u>							
1	W951T0703A17M4SNAS	95% 1 Stage 70kbtu Multi Pos Furnace	125017	S100770892	WAT	lower left side and back damage	\$900	Image Link

ALL ITEMS ARE FOR IMMEDIATE SHIPMENT-ALL SALES ARE FINAL